

KX95122-1 part list

P/N	Description	Quananity
1	Screw M5*20	8
2	Spring Washer $\phi 5$	8
3	Gearbox End Cover	1
4	Pin $\phi 3$	2
5	Screw M6*10	1
6	Clutch Handle Pin	1
7	Clutch Handle Spring	1
8	Clutch Handle Sheath	1
9	Clutch Handle	1
10	Clutch Handle Screw M4*16	1
11	O-Ring $\phi 10$	1
12	Bearing	1
13	Sun Gear	1
14	Small Ring Gear	1
15	Retainer Ring(small)	1
16	Ring Gear	1
17	Retainer Ring(big)	1
18	1st Planetary Gear Assembly	1
19	2nd Planetary Gear Assembly	1
20	Washer	1
21	3rd Planetary Gear Assembly	1
22	Power Cord	1
23	Socket Cover	1
24	Control Box Cover	1
25	Socket	1
26	Solenoid	1
27	Sheath	4
28	Screw M5*16	4
29	Control Box Top Cover	1
30	Control Box Base Cover	1
31	Tie bar	1
32	Flat Washer $\phi 16$	4

P/N	Description	Quananity
33	Screw M8*30	4
34	Motor Assembly	1
35	Motor Base	1
36	Brake Assembly	1
37	Drive Shaft	1
38	Wire Rope	1
39	Drum	1
40	Screw M5*16	8
41	Spring Washer $\phi 5$	8
42	Gasket Ring	2
43	Sliding Bearing	2
44	Gearbox Cover	1
45	O-Ring $\phi 122$	1
46	Gearbox Housing	1
47	O-Ring $\phi 122$	1
48	Ring Gear	1
49	Screw M12*25	2
50	Flat Washer $\phi 12$	2
51	Spring Washer $\phi 12$	2
52	Nut M12	2
53	Roller Fairlead	1
54	Handle Switch Assembly	1
55	Hook	1
56	Hand Saver Strap	1
57	Circuit Breaker	3
58	Circuit Breaker Connection Plate	2
59	Nut M10	4
60	Flat Washer $\phi 10$	4
61	Spring Washer $\phi 10$	4
62	Screw M10*30	4
63	Wireless Remote	1
64	Wireless Remote receiver	2

