

KW95122-1 part list

P/N	Description	Quanity
1	Screw M12*25	2
2	Flat Washer φ12	2
3	Spring Washer φ12	2
4	Nut M12	2
5	Roller Fairlead	1
6	Screw M4*16	10
7	Spring Washer φ4	10
8	Gearbox End Cover	1
9	Seal	2
10	Bearing	1
11	Sun Gear	1
12	1st Planetary Gear Assembly	1
13	Ring Gear	1
14	2nd Planetary Gear Assembly	1
15	Washer	1
16	Ring Gear	1
17	3rd Planetary Gear Assembly	1
18	Gearbox Housing	1
19	Clutch Handle Pin	1
20	O-Ring φ11	1
21	Clutch Handle Spring	1
22	Clutch Handle Base	1
23	Clutch Handle	1
24	Clutch Handle Screw M4*16	1
25	Screw M8*25	2
26	Tie bar	2
27	Gearbox Cover	1
28	Spring Washer φ4	10
29	Screw M4*16	10

P/N	Description	Quanity
30	Drum	1
31	Gasket Ring	2
32	Sliding Bearing	2
33	Brake Assembly	1
34	Motor Base	1
35	Motor Assembly	1
36	Drive Shaft	1
37	Power Lead	1
38	Control Box Assembly	1
39	Screw M8*25	2
40	Handle Switch Assembly	1
41	Wire Rope	1
42	Hook	1
43	Hand Saver Strap	1
44	Circuit Breaker	3
45	Circuit Breaker Connection Plate	2
46	Socket Cover	1
47	7 Pin Socket	1
48	Control Box Top Cover	1
49	Solenoid	1
50	Control Box Base Cover	1
51	Power Cord	1
52	Wireless Remote receiver	1
53	Wireless Remote	2
54	Nut M10	4
55	Flat Washer φ10	4
56	Spring Washer φ10	4
57	Screw M10*30	4

